



SGS REFERENCE PROJECTS WIND POWER INDUSTRY

CLIENT	PROJECT	SCOPE OF SERVICE	EQUIPMENT	EXECUTION COUNTRY	YEAR
Acciona Wind Power	Tatanka Wind Farm Project, South Dakota, USA	Health & Safety consultancy and on-site inspections to verify compliance with OSHA regulations	120 x 1.5 MW Wind Turbine Onshore Wind Farm	USA	2007
Belwind Offshore Energy	Bligh Bank Offshore Wind Farm, Belgium	Technical Consultancy, QA/QC Management Services, QA/QC Inspections	Vestas V90 wind turbines	Germany	2008 - ongoing
Edison Mission Energy		Process Quality Audit and Manufacturing Inspections	Gear Boxes	Germany	2008
		Process Quality Audit and Manufacturing Inspections	Tower and Nacelle	India	2008
	Buffalo Bear and Elkhorn Ridge Wind Farms, USA	Construction Supervision, Walk Downs and Commissioning Inspections	9 Suzlon S88 Wind Turbines and 27 Vestas V90 Wind Turbines	USA	2008 - 2009
Elsam	Burbo Offshore Wind Farm, UK	Coating Inspection	Monopiles	Belgium	2006
	Horns Rev Offshore Wind Farm, Denmark	Failure Analysis of Coating Problems & Technical Assistance for Repair Works	Monopiles, Transition Pieces, Towers, Boat Landings, Platform	Belgium	2004
EnBW Energie Baden-Württemberg AG	4 Offshore Wind Farms, Germany	Technical Due Diligence	Offshore Wind Farms	Germany	2008

OWNERS/DEVELOPERS/OPERATORS



SGS REFERENCE PROJECTS WIND POWER INDUSTRY

CLIENT	PROJECT	SCOPE OF SERVICE	EQUIPMENT	EXECUTION COUNTRY	YEAR
Enel		QA Inspections	Blades, Cables, Generators, Towers	Spain, Italy, Brazil	2003 - 2005
ENOVA	Delta Nordsee (Delta II) Offshore Wind Farm, Germany	Project Certification		Germany	2009 - ongoing
Grupo Enersis	Several Onshore Wind Farms, Portugal	Construction Supervision, Fiscalisation	Cables, Foundations, Towers, Nacelles, Hubs, Blades	Portugal	2004 - 2005
John Deere Wind Energy	Sunray and Brewster Wind Farms, USA	End of Warranty Inspections, Compliance to OSHA, NEC and NEMA, In-Service Inspections	Suzlon S64 Wind Turbines	USA	2008 - ongoing
	Pipestone, Minnesota	Review of repair procedures for fiberglass work on Wind Turbine Blades and Nacelle	Suzlon S64 and S88 wind turbines	USA	2008
LCO Nature c/o Evelop Germany GmbH	Albatros Offshore Wind Farm, Germany	Project Certification	Offshore Wind Farms	Germany	2008 - ongoing
PEP - Polish Energy Partners	Puck, Suwalki and Tychowo Onshore Wind Farm, Poland	Owners Representative, QA Inspections of Material & Equipment, Assembly Supervision, Construction Supervision, Final Inspection	Components and complete Wind Turbines	Poland	2005 - ongoing



SGS REFERENCE PROJECTS WIND POWER INDUSTRY

CLIENT	PROJECT	SCOPE OF SERVICE	EQUIPMENT	EXECUTION COUNTRY	YEAR
Plambeck Neue Energien AG	Gode Wind II Offshore Wind Farm, Germany	Project Verification - Design Basis & Site Assessment, Site Specific Design of Wind Turbine and Foundation	Offshore Wind Turbines	Germany	2008 - ongoing
PROKON Nord Energiesysteme GmbH	Borkum West II and MEG I Offshore Wind Farms, Germany	Project Certification	Offshore Wind Farms	Germany	2008 - ongoing
	Cote d'Albatre Offshore Wind Farm, France	Project Certification, Manufacturing Surveillance	Offshore Wind Farms	Germany, France	2008 - ongoing
Senter Novem	Egmond aan Zee Offshore Wind Farm, the Netherlands	Measurement Data Inspection and Validation		The Netherlands	2009 - ongoing
Skypower Cooperation		Technical Due Diligence	Onshore Wind Turbines	Germany	2007 - ongoing
Tai-Power	Changkong Onshore Wind Farm, Taiwan	Assembly Supervision, Construction Supervision, Final Inspection, NDT Supervision, Shop Inspections, Visual Inspections	2 MW Vestas V80 Wind Turbines, Towers	Denmark, Taiwan, Vietnam	2005 - 2007

OWNERS/DEVELOPERS/OPERATORS



SGS REFERENCE PROJECTS WIND POWER INDUSTRY

CLIENT	PROJECT	SCOPE OF SERVICE	EQUIPMENT	EXECUTION COUNTRY	YEAR
Vattenfall	Kriegers Flak - Offshore Wind Farm, Sweden	Design Assessment, QA Inspections and NDT of Materials & Equipment, Assembly Supervision, Final Inspection, Installation Supervision, Commissioning, Project Certification	Cables, Foundations, Towers, Blades, Gearbox, Wind Turbine, Transformer, Offshore Substation	Germany	2006 - ongoing
WE Energies	Blue Sky Green Field	Electrical walk down and Commissioning Inspection	80 onshore wind turbines	USA	2008